

FLYNT
PUMP COMPANY

REPAIR FOR
PARTS
1911 1935
1915



MKIII SERIES
PUMPS
LESS VOLUTE
FLYNT PUMP CO

1900 / 1600 SERIES REPLACEMENT PUMPS LESS VOLUTE

FLYNT	TACO	HP	IMP DIA
MKIII1125PLV	1911 / 1611 / 1600	1/4	SPECIFY
MKIII1133PLV	1911 / 1611	1/3	SPECIFY
MKIII10PLV	1610	1/3	4.50"
MKIII1150PLV	1911 / 1611	1/2	SPECIFY
MKIII1175PLV	1911 / 1611	3/4	SPECIFY
MKIII1110PLV	1911 / 1611	1	SPECIFY
MKIII1533PLV	1915 / 1615	1/3	SPECIFY
MKIII1550PLV	1915 / 1615	1/2	SPECIFY
MKIII12PLV	1612	1/2	5.75"
MKIII1575PLV	1915 / 1615	3/4	SPECIFY
MKIII14PLV	1614	3/4	6.35"
MKIII1510PLV	1915 / 1615	1	SPECIFY
MKIII1515PLV	1915 / 1615	1 1/2	SPECIFY
MKIII3550PLV	1935 / 1635	1/2	SPECIFY
MKIII30PLV	1630	1/2	4.90"
MKIII3575PLV	1935 / 1635	3/4	SPECIFY
MKIII32PLV	1632	3/4	5.65"
MKIII3510PLV	1935 / 1635	1	SPECIFY
MKIII32PLV	1634	1	6.15"
MKIII3515PLV	1935 / 1635	1 1/2	SPECIFY

- ALL MARK III PUMPS ARE SINGLE PHASE, DUAL VOLTAGE, TEFC STANDARD
- STANDARD CONSTRUCTION INCLUDES COMPOSITE IMPELLER; STAINLESS STEEL OPTIONAL ON MODEL "35" UP TO 5.65"
- ALL MARK III PUMPS AVAILABLE IN 3 PHASE
- ALL PUMPS NOT NOTED WILL BE SHIPPED WITH FULL DIAMETER IMPELLER UNLESS SPECIFIED



P U M P C O M P A N Y

MKIII to "1900" REPAIR PARTS CROSSOVER SHEET

FLYNT	TACO
IMPELLER WASHER	
151IMPW	1600-151RP
IMPELLER BOLT	
215IMPBLT	1600-215RP
WATER SEAL KIT	
MKIISLK	1600-868CRP
MKIISLKSC	1600-868SRP
SHAFT SLEEVE (!)	
205SSLV	1600-205RP
SHAFT ADAPTER	
MKIISSA	1900-008RP

FLYNT	TACO
IMPELLERS - COMPOSITE (*)	
MKII2511N	1611-001SRP 4"-4.75"
MKII2515N	1615-001SRP 4.70"-6.35"
MKII2535N	1635-001SRP 4.10"-6.15"
IMPELLERS - STAINLESS STEEL (*)	
MKII2535S	1635-001SRP 4.10"-5.65"
MKII2541S	1641-001SRP 5.90"-7.90"

FLYNT	TACO
BRACKETS	
MKIIIBRKT-E	1900-015RP, 1900-017RP
MKIIIBRKT-F	1900-002RP, 1900-019RP
BRACKET ASSEMBLY INCLUDES - SEAL, IMP BOLT, WASHER & GASKET	
MKIIIBA-E	1911
MKIIIBA-F	1915, 1935

FLYNT	TACO
BODY GASKETS	
MKIIBG-A	1600-024RP
MKIIBG-B	133-014RP
MKIIBG-D	1618-006RP
FLANGE KITS	
FP-200K	1600-032RP, 1600-032SRP
FP-250K	1600-033RP, 1600-033SRP
FLANGE GASKETS	
MKIIFGKT2	1600-009RP
MKIIIOGKT2	1600-169RP

MOTOR ASSEMBLY, 1800 RPM, 1PH INCLUDES SHAFT ADAPTER		
FLYNT	TACO	MOTOR SPEC
MKIIIM25-1	121-499RP	115/208/230/60/1 .25 HP (+)
MKIIIM33-1	131-292RP	115/208/230/60/1 .33 HP (+)
MKIIIM50-1	132-269RP	115/208/230/60/1 .50 HP (+)
MKIIIM75-1	133-375RP	115/208/230/60/1 .75 HP (+)
MKIIIM10-1	138-266RP	115/208/230/60/1 1 HP (+)
MKIIIM15-1	138-269RP	115/208/230/60/1 1.5 HP (+)
MOTOR ASSEMBLY, 1800 RPM, 3PH INCLUDES SHAFT ADAPTER		
FLYNT	TACO	MOTOR SPEC
MKIIIM25-3	121-401RP	208/230/460/60/3 .25HP (++)
MKIIIM33-3	131-294RP	208/230/460/60/3 .33HP (++)
MKIIIM50-3	132-271RP	208/230/460/60/3 .50HP (+)
MKIIIM75-3	133-377RP	208/230/460/60/3 .75HP (+)
MKIIIM10-3	138-268RP	208/230/460/60/3 1HP (+)
MKIIIM15-3	138-271RP	208/230/460/60/3 1.5HP (+)
MKIIIM20-3	138-274RP	208/230/460/60/3 2HP (+)
MKIIIM30-3	1662-028	208/230/460/60/3 3HP (+)

(!) NOT REQUIRED ON MKII/III SERIES PUMPS OR WHEN ORDERING MKIISSA
 (*) IF IMPELLER DIAMETER IS NOT SPECIFIED, FULL TRIM IMPELLER WILL BE PROVIDED
 (+) TEFC
 (++) TENV

FLYNT

P U M P C O M P A N Y

4410 W UNION HILLS DRIVE
SUITE 7-234
GLENDALE, AZ 85308
1-877-435-9682
info@flyntpumpco.com

WWW.FLYNTPUMPCO.COM