



FLYNT PUMP CO

FP SERIES

CROSS

REFERENCE

GUIDE

IMPELLERS - COMPOSITE					
FLYNT	ARMSTRONG		B&G		TACO PRO-FIT
FP-N35	S-35, H-32	816322-011, 816322-041 816322-111	2" , HV	118668, 118436 189128	IMP-B-100
FP-N45	S-45	816305-028, 816305-058 816305-328	2 1/2" , LD3	118676 118440	IMP-C-101
FP-N46	S-46	816305-025, 816305-055 816305-321	HD3	118675 118439	IMP-C-102
FP-N475	S-55	816304-021, 816304-051 816304-317	PD-35	118630 118627	IMP-D-100
FP-N525	S-57 , H-54	816304-017, 816304-047 816304-317	PD-37 , 60-14	118629 118626	IMP-D-101
FP-N51	H-51	816302-019, 816302-049 816302-319	60-11	186441, 186359 186360	IMP-D-102
FP-N52	H-52	816302-017, 816302-047 816302-317	60-2	186441 186359	IMP-D-103
FP-N53	H-53	816303-017, 816303-047 816303-317	60-13	P61010 186368	IMP-D-104

IMPELLERS - STAINLESS STEEL					
FLYNT	ARMSTRONG		B&G		TACO PRO-FIT
FP-SS45	S-45	816305-028, 816305-058 816305-328	2 1/2" , LD3	118676 118440	IMP-C-101
FP-SS475	S-55	816304-021, 816304-051 816304-317	PD--35	118630 118627	IMP-D-100
FP-SS525	S-57, H-54	816304-017, 816304-047 816304-317	PD-37 , 60-14	118629 118626	IMP-D-101

* HEADER PUMP IMPELLERS				
DIAMETER	FLYNT COMPOSITE	FLYNT STAINLESS	ARMSTRONG	TACO PRO-FIT
4 1/4"	FP-N425	FP-SS425	816304-325	IMP-D-105
4 1/2"	FP-N450	FP-SS450	816304-329	IMP-D-106

FP SERIES REPAIR PARTS CROSSOVER SHEET

BEARING ASSEMBLIES					
FLYNT	ARMSTRONG		B&G		TACO PRO-FIT
FP-35BA	S-35, H-32	816549-091 & MF	2" , HV	189100, 189101, 189102 189103, 189162, 189162	BRG-B-100
FP-45BA	S-45 , S-46, H-41	816027-002 & MF	2 1/2" , LD3, HD3, PR	189105, 189106, 118447	BRG-C-100
FP-560BA	S-55, S-57, H-54 H-51, H-52, H-53	816032-000	PD-35, PD-37, 60-14 60-11, 60-2, 60-13	186863, 186864	BRG-D-100

BEARING ASSEMBLIES WITH IMPELLER					
FLYNT	ARMSTRONG		B&G		TACO PRO-FIT
FP-35BWI	S-35, H-32	810119-003 & MF	2" , HV	N/A	N/A
FP-45BWI	S-45	N/A	2 1/2" , LD3	N/A	N/A
FP-46BWI	S-46	N/A	HD3	N/A	N/A
FP-560BA55N	S-55	N/A	PD-35	N/A	N/A
FP-560BA57N	S-57 , H-54	N/A	PD-37 , 60-14	N/A	N/A
FP-560BA51N	H-51	N/A	60-11	N/A	N/A
FP-560BA52N	H-52	N/A	60-2	N/A	N/A
FP-560BA53N	H-53	N/A	60-13	N/A	N/A

FP SERIES REPAIR PARTS CROSSOVER SHEET

MOTOR ASSEMBLIES, 115/60/1 , 1725 RPM, CCW ROTATION					
FLYNT	ARMSTRONG		B&G		TACO PRO-FIT
FP-350MTR	S-35, H-32, H41	817025-001	1 1/2" , 2" , HV, PR	111036 111031	MOT-B-100S
FP-450MTR	S-45	817025-007	2 1/2" , LD3	111040	MOT-C-100S
FP-460MTR	S-46	817025-013	HD3	111042	MOT-C-101S

MOTOR ASSEMBLIES, 115/230/60/1, 1725 RPM, ODP, REV					
FLYNT	ARMSTRONG		B&G		TACO PRO-FIT
FP-56050MTR	H53, S-55	811757-001	60-13, PD-35	111044	MOT-D-102S
FP-56075MTR	H-54, S-57	811757-002	60-14, PD-37	111047	MOT-D-104S

MOTOR ASSEMBLIES, 115/230/60/1, 1725 RPM, TE					
FLYNT	ARMSTRONG		B&G		TACO
FP-S3403	H-51	816141-001	60-11	169035	MOT-D-100S
FP-S3501	H-52	816141-002	60-2	169038	MOT-D-101S
FP-S3504	H-53, S-55	811757-001	60-13, 60-15, PD-35	111044	MOT-D-102S
FP-S3507	H-54, S-57	811757-002	60-14, 60-16, 60-18 PD-37	111047	MOT-D-104S
FP-S3510	H-65, H-67, S-69	816141-001, 811757-028	60-17, 60-19, PD-39	169232, 111050	MOT-EFG-200
FP-S3514	H-68	816678-062	60-20	169005 169236, 169095	MOT-EFG-202

FP SERIES REPAIR PARTS CROSSOVER SHEET

MOTOR ASSEMBLIES, 208/230/460/60 3 PHASE, 1800 RPM, TE					
FLYNT	ARMSTRONG		B&G		TACO
FP-S3454	H-51	N/A	60-11	N/A	N/A
FP-S3534	H-52	N/A	60-2	N/A	N/A
FP-S3538	H-53, S-55	831011-83, 811757-020	60-13, 60-15, PD-35	111046	MOT-D-103
FP-S3542	H-54, S-57	831012-083, 811757-024	60-14, 60-16, 60-18 PD-37	111049	MOT-D-105
FP-S3546	H-65, H-67, S-69	811757-028, 816676-069	60-17, 60-19, PD-39	169089, 169090 111051	MOT-EFG-201
FP-S3554	H-68	816678-069	60-20	169091, 169092 111052, 169237	MOT-EFG-203
FP-S3558	2D	816681-069	60-21	169094, 169238	MOT-FG-204
FP-S3561			60	169234	MOT-FG-205

PUMPS LESS VOLUTE 115/230/60 SINGLE PHASE					
FLYNT	ARMSTRONG		B&G		TACO
FP-35LV	S-35, H-32	110116-201	HV, 2"	N/A	RPK-B-101S
FP-45LV	S-45	110116-203	2 1/2", LD3	N/A	RPK-C-101S
FP-46LV	S-46	110116-204	HD3	N/A	RPK-C-102S
MKIVAT3E1	S-55	110116-306	PD-35	N/A	RPK-D-100S
MKIVBT5E1	H-54, S-57	110116-304	PD-37, 60-14	N/A	RPK-D-101S
MKIVGT7E1	H-51	110116-300	60-11	N/A	RPK-D-102S
MKIVFT8E1	H-52	110116-301	60-2	N/A	RPK-D-103S
MKIVAT9E1	H-53	110116-302	60-13	N/A	RPK-D-104S

FP SERIES REPAIR PARTS CROSSOVER SHEET

PUMPS LESS VOLUTE 208/230/460/60 3 PHASE, TE

FLYNT	ARMSTRONG		B&G		TACO
MKIVAT3E3	S-55-3	110116-307	PD-35T	N/A	RPK-D-200
MKIVBT5E3	H-54-3, S-57-3	110116-305	PD-37T, 60-14T	N/A	RPK-D-201
MKIVGT7E3	H-51-3	N/A	60-11T	N/A	N/A
MKIVFT8E3	H-52-3	N/A	60-2T	N/A	N/A
MKIVAT9E3	H-53-3	110116-303	60-13T	N/A	RPK-D-204

BODY GASKETS

FLYNT	ARMSTRONG		B&G		TACO
FBG-25	S-25	104442-00	75, 100, 150	P04080	GSK-A-100
FBG-35	S-35, H-32	106049-000	1 1/2", 2", HV	P04890	GSK-B-100
FBG-45	S-45, S-46, H-41	106050-000	2 1/2", LD3, HD3, PR	P05800	GSK-C-100
FBG-55	S-55, S-57, H-51, H-52, H-53, H-54	106158-000	PD-35, PD-37, 60-11 60-2, 60-13, 60-14	P57410	GSK-D-100
FBG-RPK	N/A	N/A	N/A	N/A	



4410 W UNION HILLS DRIVE
SUITE 7-234
GLENDALE, AZ 85308
1-877-435-9682
info@flyntpumpco.com

Visit our website at www.flyntpumpco.com