

FLYNT PUMP CO.

RAYPAK PUMP

CROSS REFERENCE



P U M P C O M P A N Y

FLYNT to "RAYPAK" REPAIR PARTS CROSSOVER SHEET

HEADER MOUNTED PUMPS

FLYNT	RAYPAK	HP	VOLTAGE	IMPELLER DIA
MKIVAT6E	1630-S50L , 009296F	1/2	115/230/1	4"
MKIVAT1E	1630-S33L , 004844F	1/2	115/230/1	4.25"
MKIVAT3E	1630-S34L , 004845F	1/2	115/230/1	4.75"

INLINE CIRCULATORS , PUMPS LESS VOLUTE

FLYNT	RAYPAK	HP	VOLTAGE	IMPELLER DIA
MKIII1125PLV	007226F , 007227F, 007232F 007233F , 950609 , 950606	1/4	115/230/1	4.5"
MKIII30PLV	007347F , 007353F , 011845F 011846F, 950639, 950636	1/2	115/230/1	4.9"
MKIII32PLV	007348F , 007354F , 007355F 007356F , 950645 , 950642	3/4	115/230/1	5.65"
MKIII34PLV	007351F , 007357F 950648 , 951288	1	115/230/1	6.15"
MKII36PLV	007937F , 007938F , 950657	1 1/2	115/230/1	6.40"
MKII38PLV	012317F , 012318F , 951276	2	115/230/1	6.90"

INJECTOR PUMPS , LESS VOLUTE

FLYNT	RAYPAK	HP	VOLTAGE	IMPELLER DIA
MKIIIR25PLV-3	951414 , 951415	1/4	208/230/460/3	4"
MKIIIR33PLV-3	012669F , 951413	1/3	208/230/460/3	4.60"
MKIIIR75PLV-3	012668F , 951411 , 951416	3/4	208/230/460/3	5.20"

OEM PART NUMBERS LISTED IN THIS CROSS REFERENCE ARE BELIEVED TO BE ACCURATE AT TIME OF PRINTING AND ARE FOR INFORMATIONAL USE ONLY. VERIFY MODEL, VOLTAGE, HP AND IMPELLER DIAMETER BEFORE ORDERING.



P U M P C O M P A N Y

FLYNT to "RAYPAK" REPAIR PARTS CROSSOVER SHEET

FLYNT	RAYPAK
"BEARING" ASSEMBLY, COMPLETE	
FP-RPKBA	1630-079RP
MKIIBA-A	INCLUDES KIT #'S: 015286F 950388F, 015299F, 015301F
MKIIBA-B	INCLUDES KIT #'S: 015287F 950388F, 015299F, 015301F
MKIIBA-C	INCLUDES KIT #'S: 015288F 950388F, 015299F, 015301F
MKIIBA-D	INCLUDES KIT #'S: 015289F 950388F, 015300F, 015301F
MKIIBA-E	INCLUDES KIT #'S: 015290F 950388F, 951086F, 15299F
MKIIBA-F	INCLUDES KIT #'S: 015291F 950388F, 951086F, 15299F

FLYNT	RAYPAK
BODY GASKETS	
MKIIBG-A	1600-024RP
MKIIBG-BC	133-014RP
MKIIBG-D	1618-006RP
FLANGE KITS	
FP-200K	015538F, 015539F
FP-250K	014047, 014048
FLANGE GASKETS	
MKIIFGKT2	012666F
MKIIOGKT2	013423F

FLYNT	RAYPAK	
SHAFT ADAPTER		
MKIIISSA	015318F	
IMPELLERS - COMPOSITE		
MKII25R25N	015516F	4.00"
MKII2510N	015292F	4.50"
MKII25R33N	015517F	4.60"
MKI400N	951420F	4.00"
MKI425N	950234F	4.25"
MKI475N	951079F	4.75"
MKII2530N	015293F, 015298F	4.90"
MKII25R75N	015395F	5.20"
MKII2532N	015294F	5.65"
MKII2534N	015295F	6.15"
IMPELLERS - STAINLESS STEEL		
MKI400SS	951420F	4.00"
MKI425SS	950234F	4.25"
MKI475SS	951079F	4.75"
MKII2530S	015293F, 015298F	4.90"
MKII25R75S	015395F	5.20"
MKII2532S	015294F	5.65"
MKII2536S	015296F	6.40"
MKII2538S	015297F	6.90"

MOTOR ASSEMBLY		
FLYNT	RAYPAK	MOTOR SPEC
MKI501750R	95185F, 95189F 950919F	.50HP 115/230/60/1
MKII75MTR	950922F	.75HP 115/230/60/1
MKII10MTR	950925F	1HP 115/230/60/1
MKII15MTR	015303F	1.5HP 115/230/60/1
MKII29MTR	015305F	2HP 115/230/60/1
MKIII3454	015308F	208/230/460/60/3 .25HP (++)
MKIII3534	015310F	208/230/460/60/3 .33HP (++)
MKIII3538	015312F	208/230/460/60/3 .50HP (+)
MKIII3542	015314F	208/230/460/60/3 .75HP (+)
MKIII3546	015316F	208/230/460/60/3 1HP (+)
MKIII3514	015317F	208/230/460/60/1 1.5HP (+)

FLYNT	RAYPAK
WATER SEAL KIT	
MKIISLK	950388F
SHAFT SLEEVE (!)	
205SSLV	951086F
CARTRIDGE ASSEMBLY	
MKIIBA-M	015301F

FLYNT	RAYPAK
COUPLERS & INSERTS	
3JE-1258	015397F
4JE-5858	950389F
3JE-SLV	015284F
4JE-SLV	015285F

+TEFC 56C MOTOR, PROVIDED W/SHAFT ADAPTER
 ++TENV 56C MOTOR PROVIDED W/SHAFT ADAPTER
 (!) NOT REQUIRED WITH MKII & MKIII

FLYNT



P U M P C O M P A N Y

4410 W UNION HILLS DRIVE
SUITE 7-234
GLENDALE, AZ 85308
1-877-435-9682
info@flyntpumpco.com

WWW.FLYNTPUMPCO.COM